

Technical Advisory Bulletin (TAB)

Bulletin #: TBBE1603A

February 27, 2015

Product: MELCO WIDE ANGLE CAP FRAME DRIVER OPTION


Implementation: ☐ Urgent ☐ Mandatory ☒ As Required ☐ Info Only

Reference: N/A

Subject: Wide Angle Cap Driver (Red) Cap Supports

SITUATION:

After receiving numerous feedback from customers, trainers, technicians and other Melco staff, it was decided to no longer include the Cap Support Assembly, shown below, on the Wide Angle Cap Driver Assembly. In most cases, the Cap Supports have been removed by customers based on application experience or on recommendation by Melco.



The following Melco Options are affected by this change:

- 34259 WACF DRIVER RED & WACF (2)
- 34130 DRIVER, RED, WACF

The Cap Support Assembly includes the following part numbers:

- 34173, 34172, 34171, 34170, 34168 and related fasteners.

Copyright © BERNINA, 2015

ALL RIGHTS RESERVED - Produced for communicating technical information to BERNINA service representatives and other authorized BERNINA technical personnel. Redistribution of this publication is prohibited without the prior written approval of BERNINA.

All precautions have been taken to avoid errors or misrepresentations of facts, equipment, or products. However, BERNINA does not assume any liability to any party for loss or damage caused by errors or omissions.

SOLUTION:

For those customers who require the Cap Support Assembly for their application, it can still be purchased separately. The Melco part number is 34665.

RECOMMENDED ACTION:

Existing customers can be instructed to remove the Cap Support Assembly as required to help solve cap sew quality issues. Inform new and existing customers that the Cap Support Assembly is available to order for special applications as identified in the Parts Manual and installation instructions are in the Operators and Technical Manuals.