

Technical Advisory Bulletin (TAB)

Bulletin #: TBBEE1617A

December 14, 2017

Product: BERNINA E16

Implementation: ☐ Urgent ☐ Mandatory ☐ As Required ☒ Info Only

Reference: N/A

Subject: New Location for Closest / Farthest Needle Gap Information

SITUATION:

Currently, the closest/farthest needle gap information is written on the inside of the Base Enclosure.

IMPLEMENTED CHANGE:

The location for the closest/farthest needle information has been changed to the underside of the Upper Arm Casting. See below.



RECOMMENDED ACTION:

No action is required. This TAB is for information only.

Copyright © BERNINA, 2017

ALL RIGHTS RESERVED - Produced for communicating technical information to BERNINA service representatives and other authorized BERNINA technical personnel. Redistribution of this publication is prohibited without the prior written approval of BERNINA.

All precautions have been taken to avoid errors or misrepresentations of facts, equipment, or products. However, BERNINA does not assume any liability to any party for loss or damage caused by errors or omissions.