

Technical Advisory Bulletin (TAB)

Bulletin #: TBBEE1619A

April 3, 2018

Product: BERNINA E16

Implementation: ☐ Urgent ☐ Mandatory ☒ As Required ☐ Info Only

Reference: EC3341

Subject: Control Board Field Replacement

SITUATION:

The BERNINA E16 machine model was initially released equipped with the 34543 Control Board PCBA. The Control Board PCBA has since been changed to PNs 34801D. This TAB outlines the steps to be taken if an old 34543 Control Board PCBA needs to be replaced with a new 34801D Control Board PCBA.

Applicable machine serial number ranges:

BERNINA E16: 120360000 - 120361034

SOLUTION:

For Control Board PCBA replacements as indicated above for BERNINA E16 please refer to instruction document 34918, "New Control Board PCBA Field Replacement Instructions for BERNINA E16".

RECOMMENDED ACTION:

N/A