

Technical Advisory Bulletin (TAB)

Bulletin #: TBMELCO11A

February 25, 2016

Product: Melco EMT16, BRAVO2

Implementation: ☐ Urgent ☒ Mandatory ☐ As Required ☐ Info Only

Reference: EC3351

Subject: P/N 34326 Hook Adapter Flange


SITUATION:

Currently, if a 34326 Hook Adapter Flange needs to be replaced in the field, Melco sends out the 34326 Hook Adapter Flange and the 006390-06 Dowel Pin as separate items. In doing so the technician is then required to press the Dowel Pin into the Hook Adapter Flange before being able to install the Assembly into the machine. Pressing the Pin into the Flange is very difficult because the Dowel Pin is very small and awkward to handle. In addition, proper installation requires an arbor press which a technician in most cases will not have access to.



SOLUTION:

Melco has created a new assembly, P/N 34834, consisting of the 3mm Dowel Pin pre-installed into the 34326 Hook Adapter Flange.



RECOMMENDED ACTION:

In the case a 34326 Hook Adapter Flange needs to be replaced in the field, P/N 34834, Hook Adapter Flange w/ Pin, must be ordered.

In addition, the International Warranty Parts Kit, P/N 33853-03, has been updated replacing P/N 34326 and P/N 006390-06 (Qty 2) with P/N 34834.