

Technical Advisory Bulletin (TAB)

Bulletin #: TBMELCO21A

December 14, 2017

Product: Melco EMT16, BRAVO


Implementation: ☐ Urgent ☐ Mandatory ☐ As Required ☒ Info Only

Reference: N/A

Subject: New Location for Closest / Farthest Needle Gap Information

SITUATION:

Currently, the closest/farthest needle gap information is written on the inside of the Base Enclosure for both the EMT16 and BRAVO machines. However, the EMT16 requires the user to remove (4) Enclosure Cover screws to gain access to this information, see below. This is time consuming compared to the BRAVO Base Cover which removes quickly without any tools.



Copyright © Melco International LLC, 2017

ALL RIGHTS RESERVED - Produced for communicating technical information to Melco service representatives and other authorized Melco technical personnel. Redistribution of this publication is prohibited without the prior written approval of Melco International LLC.

All precautions have been taken to avoid errors or misrepresentations of facts, equipment, or products. However, Melco International LLC does not assume any liability to any party for loss or damage caused by errors or omissions.

SOLUTION:

The location for the closest/farthest needle information has been changed to the underside of the Upper Arm Casting for both the EMT16 and BRAVO Machines. See below.



RECOMMENDED ACTION:

No action is required. This TAB is for information only.