

Technical Advisory Bulletin (TAB)

Bulletin #: TBMELCO23A

April 3, 2018

Product: EMT16, BRAVO II

Implementation: ☐ Urgent ☐ Mandatory ☒ As Required ☐ Info Only

Reference: EC3341

Subject: Control Board Field Replacement

SITUATION:

The EMT16 and BRAVO II machine models were initially released equipped with the 31058-19 and the 34001 Control Board PCBA, respectively. The Control Board PCBA has since been changed to PNs 34799D and 34800D, respectively. This TAB outlines the steps to be taken if an old 31058-19/34001 Control Board PCBA needs to be replaced with a new 34799D/34800D Control Board PCBA.

Applicable machine serial number ranges:

EMT16: 400000 - 403290

BRAVO II: 340360000 – 340361141

SOLUTION:

For Control Board PCBA replacements as indicated above for EMT16 and BRAVO II please refer to instruction document 34829, “New Control Board PCBA Field Replacement Instructions for EMT16 and BRAVO II”.

RECOMMENDED ACTION:

N/A